

Message

From: Merriman Henry [hmerriman@facil.umass.edu]
Sent: 7/3/2008 9:35:45 PM
To: Stevenson, Allan (DPH) [Allan.Stevenson@state.ma.us]; Roberts, Juan [/O=COMMONWEALTH OF MASSACHUSETTS/OU=MASSMAIL-01/CN=RECIPIENTS/CN=JUANROBERTS]; slr@facil.umass.edu; jcobb@facil.umass.edu; gjseaman@schoolph.umass.edu; edwardc@schoolph.umass.edu; pgoodhind@schoolph.umass.edu; mwells@microbio.umass.edu; mlw@geo.umass.edu; howe@geo.umass.edu; Maryanne Steele [msteele@ehs.umass.edu]; mkeedy@bio.umass.edu; Sally Ives [sives@bio.umass.edu]; Popstefanija, Marija (DPH) [Marija.Popstefanija@state.ma.us]; Salem, Sharon (DPH) [Sharon.Salem@state.ma.us]; Hanchett, James (DPH) [James.Hanchett@state.ma.us]; teddi@bio.umass.edu
Subject: RE: Morrill Facade Repairs UMA08-35 - Schedule 7/2/08
Attachments: Morrill Facade repairs schedule map 7-2 job meeting.pdf; Updated Schedule on Facade Project

Attached is a work schedule look ahead for the masonry repairs at Morrill 1 and Morrill 4N. Work to remove aging marble panels from window assemblies continues at Morrill 2 and 3. Please note that the sequence for removing marble panels has changed. Lastly, the schedule indicates that the contractor will start to install the new composite panels at the west facade of Morrill 2 starting next week. The new panels will replace the old replacement plywood panels as well as the current removed marble panels to provide an improved weather-resistant, durable finish.

I have also included Sally Ives' message sent yesterday which states some differing dates than found in the attached map. I updated the map based on today's operations and the the forecasted speed to remove the remaining panels.

"This work of is shown for estimated time windows and is subject to unforeseen job conditions which may affect periodic changes. A schedule update will be issued as a result of next week's job meeting."

Happy Fourth everyone.

Henry Merriman, Jr.

Capital Project Manager

Facilities & Campus Planning

University of Massachusetts

360 Campus Center Way

Amherst, MA 01003

Phone: (413) 577-1722

Fax: (413) 545-3684

Cell: [REDACTED]

-----Original Message-----

From: Merriman Henry

Sent: Wednesday, June 25, 2008 6:03 PM

To: 'Allan Stevenson (allan.stevenson@state.ma.us)'; 'Juan Roberts (jaroberts@facil.umass.edu)'; 'Sandra L Russell (slr@facil.umass.edu)'; 'Justin Cobb (jcobb@facil.umass.edu)'; 'Gloria Seaman (gjseaman@schoolph.umass.edu)'; 'Edward J Calabrese (edwardc@schoolph.umass.edu)'; 'Paula S Goodhind (pgoodhind@schoolph.umass.edu)'; 'Maryanne Wells (mwells@microbio.umass.edu)'; 'Michael L Williams (mlw@geo.umass.edu)'; 'Marsha L Howe (howe@geo.umass.edu)'; 'Maryanne Steele'; 'mkeedy@bio.umass.edu'; 'Sally Ives'; 'Marija.Popstefanija@dph.state.ma.us';

'Sharon.salem@state.ma.us'; 'James.hanchett@state.ma.us'

Subject: RE: Morrill Facade Repairs UMA08-35 - Schedule

We reviewed the schedule updated at last week's 6/18 job meeting and saw no reason to update or look further into the future. Therefore, no changes have been made. beyond the

Henry Merriman, Jr.

Capital Project Manager

Facilities & Campus Planning

University of Massachusetts

360 Campus Center Way

Amherst, MA 01003

Phone: (413) 577-1722

Fax: (413) 545-3684

Cell: [REDACTED]

-----Original Message-----

From: Merriman Henry

Sent: Friday, June 20, 2008 11:45 AM

To: Allan Stevenson (allan.stevenson@state.ma.us); 'Juan Roberts (jaroberts@facil.umass.edu)'; 'Sandra L Russell (slr@facil.umass.edu)'; 'Justin Cobb (jcobb@facil.umass.edu)'; 'Gloria Seaman (gjseaman@schoolph.umass.edu)'; 'Edward J Calabrese (edwardc@schoolph.umass.edu)'; 'Paula S Goodhind (pgoodhind@schoolph.umass.edu)'; 'Maryanne Wells (mwells@microbio.umass.edu)'; 'Michael L Williams (mlw@geo.umass.edu)'; 'Marsha L Howe (howe@geo.umass.edu)'; 'Maryanne Steele'; 'mkeedy@bio.umass.edu'; 'Sally Ives'; 'Marija.Popstefanija@dph.state.ma.us'; 'Sharon.salem@state.ma.us'; 'James.hanchett@state.ma.us'

Subject: RE: Morrill Facade Repairs UMA08-35 - Schedule

Attached is a work schedule update look ahead for the masonry repairs at Morrill 1 and Morrill 4N. Work to remove aging marble panels from window assemblies at Morrill 2 and 3 is also shown.

This work of is shown for estimated time windows and is subject to unforeseen job conditions which may affect periodic changes. A schedule update will be issued as a result of next week's job meeting.

Henry Merriman, Jr.

Capital Project Manager

Facilities & Campus Planning

University of Massachusetts

360 Campus Center Way

Amherst, MA 01003

Phone: (413) 577-1722

Fax: (413) 545-3684

Coll: [REDACTED]